



!! Gap between heater block and bottomend and topend parts should be maximum 0,50mm when assembled.
There are Copper washers (0,80mm thick) in between which need to be squashed a bit

ASSEMBLY NOTE: Heater should face large gear side